


Pressure Chart (Low Pressure < LW > case)

● Continuous pressure


Measurement pressure range: Low pressure (2.5~10MPa)
 Pressure application condition: Time to reach the pressure 2min.
 Time of retention at the pressure 2min.



As the pressure indicated by the broken line may exceed the permissible error range, please use the data for reference purpose only.

● Momentary pressure

Measurement pressure range: Low pressure (2.5~10MPa)
 Pressure application condition: Time to reach the pressure 5sec.
 Time of retention at the pressure 5sec.



As the pressure indicated by the broken line may exceed the permissible error range, please use the data for reference purpose only.

*: Talking the temperature and humidity condition into consideration, select a curve among A, B, C and D.
 *Specifications and performance capabilities are subject to change without notice.